

Strengthening

The ability of a metal to deform depends on the ability of dislocations to move

Restricting dislocation motion makes the material stronger

Mechanisms of strengthening in single-phase metals:

- grain-size reduction
- solid-solution alloying
- strain hardening

Ordinarily, strengthening reduces ductility

Strengthening by increase of dislocation density

(Strain Hardening = Work Hardening = Cold Working)

Ductile metals become stronger when they are deformed plastically at temperatures well below the melting point.

The reason for strain hardening is the increase of dislocation density with plastic deformation. The average distance between dislocations decreases and dislocations start blocking the motion of each other.


The percent cold work (% CW) is often used to express the degree of plastic deformation:

$$\%CW = \left(\frac{A_0 - A_d}{A_0} \right) \times 100$$

where A_0 is the original cross-section area, A_d is the area after deformation.


%CW is just another measure of the degree of plastic deformation, in addition to strain.

Strain Hardening (I)





The new yield strength, σ_{yi} , is higher than the initial yield strength σ_{y0} . The reason for this effect - strain hardening.

Strain Hardening (II)



Yield strength and hardness are increasing as a result of strain hardening but **ductility is decreasing** (material becomes more brittle).

Strain Hardening (III)





Recovery, Recrystallization, and Grain Growth

- **Plastic deformation increases the dislocation density (single and polycrystalline materials) and changes grain size distributions (polycrystalline materials).**
- This corresponds to stored strain energy in the system (dislocation strain fields and grain distortions).
- When the applied external stress is removed - most of the dislocations, grain distortions and associated strain energy are retained.
- Restoration to the state before cold-work can be done by heat-treatment and primarily involves two processes: **recovery** and **recrystallization**. These may be followed by **grain growth**.

Recovery

Heating \otimes increased diffusion \otimes enhanced dislocation motion \otimes decrease in dislocation density by annihilation, formation of low-energy dislocation configurations \otimes relieve of the internal strain energy

Some of the mechanisms of dislocation annihilation:




Recrystallization (I)

- Even after recovery the grains can be strained. These strained grains of cold-worked metal can be replaced, upon heating, by strain-free grains with low density of dislocations.
- This occurs through **recrystallization – nucleation and growth of new grains**.
- The *driving force* for recrystallization is the difference in internal energy between strained and unstrained material.
- Grain growth involves short-range diffusion → the extent of recrystallization depends on both temperature and time.
- Recrystallization is slower in alloys as compared to pure metals


Recrystallization (II)

Recrystallization temperature: the temperature at which the process is complete in one hour. It is typically 1/3 to 1/2 of the melting temperature (can be as high as $0.7 T_m$ in some alloys).

The recrystallization temperature decreases as the %CW is increased. Below a "critical deformation", recrystallization does not occur.



Recrystallization (III)



Grain Growth

- If deformed polycrystalline material is maintained at annealing temperature following complete recrystallization, then **further grain growth** occurs.
- *The Driving force* is reduction of grain boundary area and hence energy Big grains grow at the expense of the small ones.
- Grain growth during annealing occurs in all polycrystalline materials (i.e. they do not have to be deformed or undergo recrystallization first).
- Boundary motion occurs by short range diffusion of atoms across the grain boundary → strong temperature dependence of the grain growth.

