



Control established with a total station and fractures mapped July 1992
 Compiled by Nils A. Johnson, 1995

This map is preliminary and has not been reviewed for conformity with U.S. Geological Survey editorial standards or with the North American Stratigraphic Code.

Fractures Produced along the Emerson Fault Zone at the Single-Tower Transmission Line during the 28 June 1992 Landers, California, Earthquakes

by
 Robert W. Fleming and Arvid M. Johnson

1997